

Annexure D

BUILDING SAFETY CERTIFICATE

No.

Dated: 21-07-2026

It is certified that the existing building DELHI CITY SCHOOL (name of the building or premises) at NH-9, Simrauli, Babughat, Hapur (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	2	3				

The building is owned/occupied by DELHI CITY SCHOOL (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Ch. N. K. (Name of Department/ Govt.) on 21-07-2026 (date of inspection) in the presence of Gautam Arora, Delhi City School (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 21-07-2026 for a period of 3 years years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on 21-07-2026 at HAPUR by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal :

Name :

Designation :

Name & Address of Department Office :

Gautam Arora
Chairman
Delhi City School
NH-09 Simrauli Hapur (U P)

Principal
Delhi City School
NH-09 Simrauli, Hapur (U P)